



ArcelorMittal Bremen GmbH
Postfach 210220
28222 BREMEN
Carl-Benz-Strasse 30
28237 BREMEN
Telefon 0421/6480
Telefax 0421/6482251

A02
CERTIFICATE

A03 Page: 01/ 01
20190003886-00

Inspection certificate 3.1 EN 10204

A05 ORIGINATOR OF THE DOCUMENT
ArcelorMittal Bremen GmbH
Abnahme/Zugunisschreibung
zeugnisse.bremen@arcelormittal.com
Telefon 0421/6482813

A09 DISPATCH NOTE
DATE

0000812560
17.01.2019

A08.1 MANUFACTURER'S ORDER NR 1832224
DATE 17.09.2018
AGENCY'S ORDER NR. FH84KON004001

A07 CUSTOMER'S ORDER NUMBER
1112254

A10 PART NUMBER
XR355038P

A06.1 CUSTOMER
OY KONTINO AB

HAKINTIE, 6
01380 VANTAA
Finland

A06.2 CONSIGNEE
OY KONTINO AB

HAKINTIE, 6
01380 VANTAA
Finland

127838



Kontino Oy Ab

PRODUCT: hot rolled pickled sheet

QUALITY: AMSTRONG 355MC
S355MC

STANDARD: AM FCE
EN 10149-2 (00-09-2013)

TERMS OF DELIVERY: EN 10051 (2010)

JITZ 1.74

A08.2 ITEM	B09 THICKNESS mm	B10 WIDTH mm	B11 LENGTH mm
1	3.00	1500.00	3000.00

A08.2 ITEM	B07.1 COIL NO	B07.1 PART	B13 WEIGHT kg	B08 AMOUNT	B07.2 HEAT	CHEMICAL ANALYSIS																	
						C71 C	C73 Si	C72 Mn	C74 P	C75 S	C77 Cu	C76 Al											
1	692344	00600	2455	23	057118	0.0750	0.0091	0.5325	0.0109	0.0053	0.0099	0.0342	0.0041	0.0001	0.0007	0.0011	0.0238	0.0221	0.0250	0.0019	0.0013	0.0009	
	4600736																						
	692344	01000	640	6	057118	0.0750	0.0091	0.5325	0.0109	0.0053	0.0099	0.0342	0.0041	0.0001	0.0007	0.0011	0.0238	0.0221	0.0250	0.0019	0.0013	0.0009	
	4600749																						
	2		3095																				
TOTAL		2		3095																			

A08.2 ITEM	B07.1 COIL NO	B07.1 PART	B13 WEIGHT kg	B08 AMOUNT	B07.2 HEAT	TENSILE TEST							BEND TEST	
						C02 PR	C04 MAZ	C03 Temp °C	C11 yield p. Re MPa	C12 strength Rm MPa	C13 A45mm %	C50 Fa		
1	692344	00600	2455	23	057118	0	F	20	408	493	33.5	1		
	4600736													
	692344	01000	640	6	057118	0	F	20	408	493	33.5	1		
	4600749													
	2		3095											
TOTAL		2		3095										

We certify hereby that the delivery complies with the above mentioned specification.



QUALITY DEPARTMENT
SITE EXPERT FOR INSPECTION
Kramer

Heiko Kramer

BREMEN 17.01.2019

C02 test direction relating to rolling direction (0°= L; 90°= T)	C04 specimen condition V: aged F: fresh N: normalised	C50 bend test 1: good
---	--	--------------------------